

2018 BOND IMPROVEMENTS*



Conifer Articulation Area

	Build new facility on same property	Expand with addition	Remodel building interior	Additions/renovators for programs	Growth accommodations	Remove modular buildings	Security camera & lock updates	Secure entries & office locations	New, more secure exterior doors	More secure & energy-efficient windows	Update existing technology	Landscaping & field improvements	Update interior paint, wall-coverings	Update electrical wiring & increase capacity	Update HVAC, plumbing & piping	Update caulking, trim & window sills	Repair & update exterior finish	New paint to protect exterior	Commercial kitchen improvements	Parking lot & sidewalk improvements	Replace old playground improvements	Replace old playground equipment	Replace old furniture	Replace old carpet & floor tile	Replace movable partitions	Replace old sinks, cabinets & shelving	Replace interior lighting with LEDs	Replace worn roofing
Conifer High		•	•	•			•	•			•	•	•	•						•		•	•	•		•		
Elk Creek Elementary							•	•			•	•	•	•							•	•	•	•		•		
Marshdale Elementary	•																											
West Jefferson Elementary							•	•			•								•			•			•			
West Jefferson Middle							•	•	•		•		•	•	•	•						•			•	•		

*Based on 2018 Capital Improvement Plan. Subject to project scope.

West Jefferson Middle School Improvements

- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- New, more secure exterior doors.
- Update existing technology for student learning.
- Update interior paint, wall-coverings.
- Update old electrical wiring, panels & increase capacity.
- Update old heating & cooling equipment, plumbing fixtures & piping.
- Replace:
 - Old sink cabinets, overhead shelving & bookcases;
 - Old student furniture & library furniture; &
 - Interior lighting with energy-efficient LEDs.



Age of Facility: 44 years (built in 1974)
Square Footage: 104,165

Enrollment: 534

**BUILDING
CONDITION:
FAIR**

FCI: 26.1%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

Good: less than 10%
Fair: 11% to 30%
Poor: greater than 30%.

Estimated cost of proposed improvements: \$2,323,535. Subject to change per final project scope.